








8160












8160N


NR	ELEMENT	8160N
E1	<div data-bbox="507 427 624 566"></div> <div data-bbox="236 573 389 607">D8160_1N</div>	1
E2	<div data-bbox="507 683 624 822"></div> <div data-bbox="236 887 389 920">D8160_2N</div>	1
E3	<div data-bbox="365 1070 683 1153"></div> <div data-bbox="236 1205 367 1238">D8160_3</div>	1
E4	<div data-bbox="408 1283 667 1491"></div>	1



8160N

Nr	Element	DIN	ELEMENT	Σ
1		-	S6x60	2
2		-	W6x60	1
21		DIN 125	8x16	1
77		-	K3_d30_A89 _G	1
232		DIN 571	16x300 (OC)	2
90		DIN 125	16x30 (OC)	2
213		-	Z_NA_1	1
214		-	Z_NA_2	1
229		-	Z_R_42	2



8160N



8160 N




ENG: „Due to the irregular shapes of natural robinia wood trunks, all dimensions provided in the documentation may slightly vary from the actual dimensions of the product.”

PL: “Z uwagi na nieregularne kształty naturalnych pni drewna robinii, wszystkie wymiary podane w dokumentacji mogą nieznacznie odbiegać od rzeczywistych wymiarów produktu.”




1

8160N




2

8160N



INST_81_0_2



3

8160N

B25 0,2m³

min. 48H

